

FIRE EXTINGUISHER INSPECTION REPORT

Location Karting North East
 Warden Law Motorsports Centre
 Hangmans Lane
 Sunderland
 SR3 2PR
 Contact Phil Bainbridge 07980613864
 phil@kartingnortheast.com

Report Number

2403 040

Planned Maintenance ☒

Call Out ☐

Delivery/Commissioning ☐

EQUIPMENT CHECKED

Qty	Type	Basic Service	Extended Service	Refilled	Overhaul	Unfit for Service	Supplied New
2	CO2 2 kg (1)	2					
4	Foam 6 litre (3)	4					
5	Powder 3 kg (5)	1				4	4
13	Powder 6 / 9 kg (13)	12				1	1
2	9kg Powder					2	2

MATERIALS SUPPLIED

Qty	Description	Price	Qty	Description	Price
26	Tamper Indicator		2	9kg Powder	
19	Hose Seal O-Ring		1	6kg Powder	
2	Co2 Horn O-Ring		5	3kg Powder	
	Safety Clip/Pin				
24	Gauge Test & Patch				

NOTES

Date 14-3-24
 Customer Signature C Wyatt
 Print C Wyatt
 Service Engineer P. [Signature]
 Order Number

Y/N/NA
 Unserviceable Extinguisher Removed ☒
 Remedial Work Required ☒
 Wall Mounted or Floor Stands ☒
 Extinguisher ID Signs in Place ☒

We hereby certify that the fire extinguishers shown above have been serviced in accordance with BS5306 Part 3.
 Customers are obliged to provide an appropriate level of fire-fighting equipment at all times. Customers are reminded it is their responsibility to check that the fire equipment is located at its normal fire points and has not been discharged or suffered obvious damage, by carrying out regular checks, preferably at monthly intervals. Customers are advised that powder extinguishers are extremely messy when discharged.
 Terms: Subject to published conditions available upon request.