

## FIRE EXTINGUISHER INSPECTION REPORT

Location Karting North East  
 Warden Law Motorsports Centre  
 Hangmans Lane  
 Sunderland  
 SR3 2PR  
 Contact Phil Bainbridge 07980613864  
 phil@kartingnortheast.com

Report Number

2503 041

 Planned Maintenance ☒

 Call Out ☐

 Delivery/Commissioning ☐

### EQUIPMENT CHECKED

Qty	Type	Basic Service	Extended Service	Refilled	Overhaul	Unfit for Service	Supplied New
2	CO2 2 kg (1)	2					
5	Foam 6 litre (3)	5					
6	Powder 3 kg (5)	6					
24	Powder 6 / 9 kg (13)	21				3	3

### MATERIALS SUPPLIED

Qty	Description	Price	Qty	Description	Price
37	Tamper Indicator	/	3	6kg Powder Extinguisher	
29	Hose Seal O-Ring	/	1	6kg Foam Extinguisher	
2	Co2 Horn O-Ring	/			
	Safety Clip/Pin				
35	Gauge Test & Patch	/			

### NOTES

Date  11/03/2017  
 Customer Signature  C Wyllie  
 Print  C WYLLIE  
 Service Engineer  Phil Bainbridge  
 Order Number

Y/N/NA  
 Unserviceable Extinguisher Removed ☒ Y  
 Remedial Work Required ☒ Y  
 Wall Mounted or Floor Stands ☒ Y  
 Extinguisher ID Signs in Place ☒ Y

We hereby certify that the fire extinguishers shown above have been serviced in accordance with BS5306 Part 3. Customers are obliged to provide an appropriate level of fire-fighting equipment at all times. Customers are reminded it is their responsibility to check that the fire equipment is located at its normal fire points and has not been discharged or suffered obvious damage, by carrying out regular checks, preferably at monthly intervals. Customers are advised that powder extinguishers are extremely messy when discharged. Terms: Subject to published conditions available upon request.